

1

HBC-28/15	PEC-TA-28/15
HBC-38/17	PEC-TA-38/17
HBC-40/22	PEC-TA-40/22, PEC-TA-40/22-P, PEC-TA-40/25
HBC-50/30	PEC-TA-49/30, PEC-TA-50/30, PEC-TA-50/30-P PEC-TA-52/34, PEC-TA-54/33

2

3

4

5

6

6

7

HBC Schraube		T _{inst} (Nm) ¹⁾			
		 4.6, 8.8, A4-50, A4-70			
			4.6	8.8	A4-50 A4-70
HBC-28/15	M8	7	-	20	7
	M10	10		40	15
	M12	13		60	30
HBC-38/17	M10	15	13	15	22
	M12	25	-	45	50
	M16	40		100	90
HBC-40/22	M10	15	13	15	22
	M12	25	-	45	50
	M16	30		100	90
HBC-50/30	M12	25	-	45	50
	M16	55		100	130
	M20	55		360	250

¹⁾ T_{inst} darf nicht überschritten werden